

IMPORTANT: Due to constant improvements in vehicle design and quality, changes to a vehicle configuration may occur which can affect the Owner's Manual information after the supply for production has already been printed.

A maintenance instruction was discovered missing in 2023 and 2024 ZFORCE 800 Trail / 950 Trail / 950 Sport and Sport-4 Owner's Manuals after supplies were already printed and inserted into production.

The instructions for applying all-season grease periodically to the front driveshaft slip-yoke were inadvertently omitted from the maintenance section. Please refer to this addendum during regular maintenance, and keep a copy with your vehicle owner's manual.

2023 ZFORCE 800 Trail / 950 Trail / 950 Sport Owner's Manual - 5BWV-380101-7100-13 US228

2024 ZFORCE 800 Trail / 950 Trail / 950 Sport / 950 Sport-4 Owner's Manual - 5BYV-380101-6200-13 US232

Driveline Maintenance

Many of the vehicle driveline components do not require regular lubrication, but owners should ensure the driveline is regularly cleaned of dirt and debris and inspected for loose or damaged components before operating the vehicle.

Driveshaft Slip-yoke Lubrication (50hrs / 6 months / 500 miles – whichever interval arrives first)

Lubricate the driveshaft slip-yoke:

1. Remove the passenger seat.
2. Remove the access panel.
3. Add lubricating grease at the driveshaft slip-yoke grease nipple (1) with a grease gun until it begins to appear at the yoke end.
4. Reinstall the access panel and passenger seat.



CFMOTO apologizes for the error, and assures consumers of our 100% commitment to the production of high-quality vehicles for powersports enthusiasts to enjoy.

The most recent version of Owner's Manuals can be found on the CFMOTO Dealer Portal or consumer website at www.cfmotousa.com.